



www.docshipper.com



DOCSHIPPER GROUP INSPECTION REPORT

Time is money. We save you both!



General Description



Product Name:	VCM-4300 Electric Vintage Car Total 9 Seats with belts(3+3+3)
Inspection location:	Old Town, Wucheng County, Dezhou City, Shandong Province
Inspection date:	May 9 2021
P/O number:	-
Inspection Type:	Pre-shipment Inspection
Ordered quantity:	4pcs
Inspected samples:	4pcs
Reference sample available:	No

Final inspection result

PENDING

(The client has the final right to make the decision.)

Inspector : Jason

Report reviewer : Jevon

Remarks

- 1 The factory had no weighing equipment, and the product cannot be weighed.
- 2 After QC arrived at the factory, four sightseeing cars had been completed, but they were not packed.
- 3 There is no logo, tag, bar code, etc. on the appearance of the product, and no product instructions or certification materials.
- 4 The products were stored in the workshop, not covered to prevent dust. The cars' body had floating ash, and the factory might clean before packaging.
- 5 The input voltage of the sightseeing car was 220V.

Advice for today's inspection

The defects were found by the inspector on the inspected samples were shown to the factory. The inspector advised the factory to repair/replace these samples.

Category	Pass	Fail	Pending	Remark
Quantity	√			Remark 2
Product specification			√	Remark 4
On-site test	√			Remark 1,5
Data measurement			√	Refer to data details
Packing			√	Refer to packing details
Marks&Labels			√	Remark 3
Factory cooperation	√			

Product check:

Item No.:	Product size L × W × H(cm)	Product N.W (kg)	UPC Barcode	Barcode scanning
VCM-4300 Electric Vintage Car	493*150*200cm	/	-	-

Export carton information:

Carton:	New export carton	/	Sealing:	Opaque gummed tape	-
Fastening:	Metal staples	/		Transparent gummed tape	-
Strapping:	Nylonx2	/		Paper tape	-
Material:	Ply of corrugated paper	/	Others:	/	/

Quantity

Item Number	Ordered Quantity	Finished Quantity	Carton quantity		Inspected quantity	
			Packed	Unpacked	Packed	Unpacked
VCM-4300 Electric Vintage Car	4pcs	4pcs	0	4pcs	0	4pcs

Inspection Standard

Inspection method	ANSI/ASQZ1.4 (MIL-STD-105E)			
Sampling plan	Single, Normal	Sample size	4pcs	
AQL II		Critical	Major	Minor
	Defects found	0	0	0
	Max limit	0	/	/
Final AQL result		Pending <i>Refer to remark 3,4</i>		

Defective List

Item	Swaddle Blankets	CRI	MAJ	MIN
1	VCM-4300 Electric Vintage Car Total 9 Seats with belts(3+3+3)	0	0	0
	Total Defects Quantity	0	0	0

Factory Picture



Product storage



Product storage

Product Specification

VCM-4300 Electric Vintage Car



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view

Product view



Product view



Product view



Product view



Product view





Instructions view



Instructions view



Product view



Product view



Product view



Product view



Product view



Product view



Product view




Product view



Product view



Product view



Product view

Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view

Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view

Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view

Product view



Product view



Product view







Product view



Product view



<p>Product view</p> 	<p>Product view</p> 
<p>Product view</p> 	<p>Product view</p> 
<p>Product view</p>	<p>Product view</p>



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view

Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view

Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view

Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view



Product view

Product view



Product view



Product view



Product view




Product view




Product view

Product view

Product view

Product view

Size measurement for the product


Size of product


Size of product



Size of product



Size of product





Size of product



Size of product



Size of product	Size of product
	
Size of product	Size of product

Test

	
Fully loaded driving test	Fully loaded driving test



Fully loaded driving test



Fully loaded driving test



Fully loaded driving test



Light test



Light test



Light test



Light test



Light test



Reverse image



Reverse image



Reverse image



Reverse image

Note: This report does not relieve suppliers from their contractual liabilities or prejudice buyers' right for compensation for any apparent and/or hidden defects that are not detected during our random inspection or occurring thereafter. And the report is only for what we find on-site which doesn't include any defects that may occur after the inspection.

--The End of Report--